

# Axial Fan and Water Pump Belts



| APPLICATION  | REPLACES      | PART #      | SUG. RETAIL |
|--|---------------|-------------|-------------|
| <b>ARCTIC CAT</b>  |               |             |             |
| 1971-75 all Kawasaki F/C engines; 1995-97 Bearcat 340  | 3001-310      | 09-300/B032 | \$3.85      |
| 1994 Cheetah 340/440; 1987-90 Jag 340; 1979-80 Jag 3000; 1990-91 Jag Mtn. Cat; 1991-93 Lynx 300/Dlx.; 1992-93 Lynx Mtn. Cat; 1994-97 Puma/Dlx./2-Up; 1979-80 Trail Cat 3000        | 3002-783      | 09-300/B032 | 3.85        |
| 1995-96 Bearcat 440; 1981-85 Jag; 1985-88 Jag 440; 1989-96 Jag/AFS/Dlx./Spec./LT/Z; 1988-91 Super Jag; 1989 Pantera; 1980-85/89-95 Panther/Dlx.; 1981 Trail Cat; 1995-96 Z440      | 3002-854      | 09-303/B032 | 3.85        |
| 1997 Bearcat 440; 1976-78 Cheetah; 1986-87 Cheetah F/C; 1989-90 Cheetah Touring; 1985-90 Cougar; 1977 Jag Dlx.; 1977-81 Pantera; 1976-79/86-88 Panther 1997 Panther 440; 1997 Z440 | 3002-156      | 09-328/B032 | 3.85        |
| 1986-88 Cheetah L/C; 1979 X-Country; 1987-88 El Tigre 5000; 1978-81/84-89 El Tigre 6000; 1989-91 El Tigre EXT; 1985-89 Pantera   | 3002-606      | 09-329/B032 | 3.85        |
| <b>CCW (Kioritz)</b>   |               |             |             |
| KEC400 (38), KEC440 (35 & 45)  | 35001010      | 09-310/B032 | 3.85        |
| KEC290 (40)  | 40001090      | 805A/B032   | 3.85        |
| KEC290 (35 & 50)   | 52900024      | 805B/B032   | 3.85        |
| KEC340 (29-55), KEC400 (except 38), KEC440 (25-35)   | 52900025      | 09-306/B032 | 3.85        |
| KEC340 (55-65); KEC440 (55); KEC400 RV (52); KEC440 RV (24)  | 55001010      | 09-307/B032 | 3.85        |
| KEC340 (65); KEC400 RV (62); KEC440 RV (34)  | 36002340      | 09-308/B032 | 3.85        |
| <b>CHAPARRAL (Xenoah)</b>  |               |             |             |
| 295/340 F/C  | 78492         | 09-309/B032 | 3.85        |
| 400/440/484 F/C  | 78294         | 09-310/B032 | 3.85        |
| 250/340/440 L/C engines  | 79103         | 803/B072    | 4.50        |
| <b>HIRTH</b>   |               |             |             |
| 270R, 271R, 272R, 273R   | 043.3/2       | 812/B074    | 7.85        |
| 280R   | 043.3/3       | 813/B074    | 7.85        |
| <b>JLO</b>   |               |             |             |
| LR340/2, LR399/2, LR440/2, 2F340-3, 2F400-3, 2F440-4   | 000-42-17-508 | 09-317/B032 | 3.85        |
| 2F292-2, 2F340-6, 2F400-8, 2F440-8   | 000-42-17-507 | 09-315/B032 | 3.85        |
| <b>KAWASAKI (SNO JET)</b>  |               |             |             |
| 1978 Inviter; 1979-80 Drifter 340  | 59011-3002    | 09-303/B032 | 3.85        |
| 1978 Intriguer; 1978-82 Intruder; 1979-81 Drifter 440; 1980-84 Sportfire; 1979-84 Trailfire  | 59011-3001    | 803/B072    | 4.50        |
| 1977 Astro 340 SS & 440 SS   | 59011-502     | 09-300/B032 | 3.85        |
| <b>KOHLER</b>  |               |             |             |
| K295-2AX, K340-2AX, K340-2LC, K440-2LC   | 40.203.01     | 09-317/B032 | 3.85        |
| K340-2AS, K440-2AS, K44-2AX  | 38.203.01     | 09-318/B032 | 3.85        |
| K250-RLC, K340-RLC, K440-RLC   | 44.203.01     | 09-319/B032 | 3.85        |
| <b>MERCURY</b>   |               |             |             |
| 1972-74 CCW, 440 SM, 440 SR  | 57-64539      | 09-306/B032 | 3.85        |
| 1974-75 Kohler 340 SR  | 57-71249      | 09-317/B032 | 3.85        |
| 1974-75 Kohler 440 Trail Twister   | 57-71206      | 09-318/B032 | 3.85        |
| <b>MOTO-SKI (BSE)</b>  |               |             |             |
| 1974 Futura 440; 1974-75 Chimo, Grand Sport  | 504-8009-73   | 09-302/B032 | 3.85        |
| 1975-79 Futura 440; 1977 Nuvik 440   | 420-9804-00   | 09-307/B032 | 3.85        |
| 1974 Futura 340  | 540-8009-69   | 09-310/B032 | 3.85        |
| 1975-79 Nuvik 300/340; 1977-79 Futura 400; 1980-84 Mirage  | 420-9804-36   | 09-317/B032 | 3.85        |
| 1973 MS-F; 1973-74 Capri; 1974 Futura; 1979 Mirage   | 420-9804-55   | 09-320/B032 | 3.85        |